## **iSMA-B-MAC36PRO**

## **Master Application Controller**

## iSMA-B-MAC36PRO Release Note 1.1

2024

| NAME                            | DESCRIPTION   |
|---------------------------------|---|
| iSMA-B-<br>MAC36PRO<br>Ver. 1.1 | <ul> <li>New supported Niagara versions:</li> <li>support of the Niagara 4.10.7 (U7);</li> <li>support of the Niagara 4.13.2 (U2);</li> </ul>   |
| Release date<br>23 July 2024    | <ul> <li>New Functionalities:</li> <li>Support for 802.1X (available in 4.13.2)</li> <li>Advanced OS Log Reading from Niagara Workbench (available in 4.13.2)</li> <li>Platform Diagnostic Servlet with OS debugging options (available in 4.13.2)</li> <li>New Niagara 4.10.7 clean-dist file</li> <li>New Niagara 4.10.7 Golden Image for iSMA-B-SD-PRO</li> </ul>  |
|                                 | <ul> <li>MAC36PRO Support:</li> <li>iC Niagara Expansion Pack 4.10.7</li> <li>iC Niagara Expansion Pack 4.13.2</li> <li>iC Workbench 4.10.7.42</li> <li>iC Workbench 4.13.2</li> </ul>  |
|                                 | <ul> <li>Improvements:</li> <li>Accelerated OS Update</li> <li>Increased User Space: Separation of OS partition from Niagara user partition.</li> <li>Enhanced system stability and reliability with dual-copy of OS partition</li> <li>Improved readability of partition names in Platform Administration</li> <li>New Fail safe mechanism for the OS update</li> </ul>  |
|                                 | <ul> <li>Other changes:         <ul> <li>Support for Niagara 4.10.6.18 will be limited. Upgrading to the latest golden image for iSMA-B-SD-PRO is recommended. Please refer to the iSMA-B-SD-PRO_Factory_State manual for guidance.</li> </ul> </li> </ul>  |
|                                 | <b>Fixed bugs:</b><br>MAC-3229 – Corrected value transfer issue in resistance measurement for unconnected U<br>9-16 inputs.   |
|                                 | Known Issues:   |
|                                 | <ul> <li>Long upgrade time - Upgrading from 4.10.6 to 4.10.7 may take an extended period It is advised to save the station configuration and reflash the iSMA-B-SD-PRO card using the new mac36pro-secureboot-imx8mp-var-dart_73.wic golden image.</li> <li>Upgrade Limitations - Direct upgrade from 4.10.6 to 4.13.2 is not supported. An intermediate upgrade to 4.10.7, or new golden image reflash is required before proceeding to 4.13.2 or later versions.</li> </ul> |
|                                 | For additional details or support, please refer to the updated documentation or contact our support at support@ismacontrolli.com  |

iSMA CONTROLLI S.p.A. - Via Carlo Levi 52, 16010 Sant'Olcese (GE) - Italy | support@ismacontrolli.com

| NAME  | DESCRIPTION  |
|---|--|
| <b>iSMA-B-</b><br><b>MAC36PRO</b><br><b>Ver. 1.0</b><br>Release date<br>24 Feb 2024 | <ul> <li>New Functionalities:</li> <li>First Release</li> <li>Niagara Versions Supported in This Installer:</li> <li>4.10.6.18;</li> </ul> |

iSMA CONTROLLI S.p.A. – Via Carlo Levi 52, 16010 Sant'Olcese (GE) - Italy | support@ismacontrolli.com