iSMA-B-MAC36NL

Master Application Controller

iSMA-B-MAC36NL Software Bundle 1.10

2024

The list below contains modifications and new features since the release of software bundle version 1.9.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.10 Release date 7 May 2024	New Functionalities:

iSMA-B-MAC36NL Software Bundle 1.9

2023

The list below contains modifications and new features since the release of software bundle version 1.8.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.9 Release date 13 July 2023	New Functionalities:

iSMA-B-MAC36NL Software Bundle 1.8

2023



The list below contains modifications and new features since the release of software bundle version 1.7.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.8 Release date 23 Feb 2023	New Functionalities:
iSMA IO Driver Ver. 2.4.0.0 Release date 23 Feb 2023	Fixed bugs: • MAC-2197 LocalIO points frozen values issue fixed Improvements: • stability improvements

iSMA-B-MAC36NL Software Bundle 1.7

2022

The list below contains modifications and new features since the release of software bundle version 1.6.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.7 Release date 17 Aug 2022	New Functionalities: • support of the Niagara 4.11.1.16 (U1); • added IEEE802.1X support (requires N4.11); • added BACnet/SC support (requires N4.11).
	 Improvements: rebranded boot and screensaver and console. Fixed Bugs: Fixed IPv6 addressing issue.
	Niagara Versions Supported in This Installer:
iSMA IO Driver Ver. 2.3.0.0 Release date 23 Mar 2022	 New Functionalities: new DigitalUniversalInput component; Polarity conversion functionality added to DigitalInput and DigitalOutput components.

iSMA-B-MAC36NL Software Bundle 1.6

7 Dec 2021



The list below contains modifications and new features since the release of software bundle version 1.5.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.6 Release date 7 Dec 2021	New Functionalities: support of the Niagara 4.10.1.36 (U1). Improvements: stability improvements. Fixed Bugs: iSMA Modbus Tunnel not working in Niagara 4.10 on iSMA-B-MAC36NL fixed in 4.10.1.36 version. Niagara Versions Supported in This Installer: 4.4.73.24; 4.6.96.28; 4.7.109.20; 4.8.0.110; 4.9.1.30; 4.10.1.36.

iSMA-B-MAC36NL Software Bundle 1.5

13 Jul 2021

The list below contains modifications and new features since the release of software bundle version 1.4.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.5 Release date 23 Jun 2021	New Functionalities:
iSMA IO Driver Ver. 2.2.0.5 Release date 8 Mar 2021	 Improvements: AO, NumericPoint, NumericWritable prints improved warning logs; stability improvements. Fixed Bugs: freezing Universal Input after language change in Local Platform Service Settings; universal input displaying only integer values of the input in Voltage mode.

iSMA-B-MAC36NL Software Bundle 1.4

16 Dec 2020

The list below contains modifications and new features since the release of software bundle version 1.3.

NAME	DESCRIPTION	DESCRIPTION



iSMA-B-MAC36NL Ver. 1.4 Release date 16 Dec 2020	New Functionalities:
iSMA IO Driver Ver. 2.2.0.3 Release date 16 Dec 2020	Improvements:
iSMA HDMI Driver Ver. 1.1.1 Release date 16 Dec 2020	 Improvements: iSMA_HDMI signed with Global Control 5 Trusted Certificate; stability improvements.

iSMA-B-MAC36NL Software Bundle 1.3

31 Mar 2020

The list below contains modifications and new features since the release of software bundle version 1.2.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.3 (Build 1152) Release date 31 Mar 2020	 New Functionalities: support of the Niagara 4.8 (distribution v. 1152); web engine: User fonts support and a pop-up control for the HDMI display; device extension auto-recognition shown in the "Product" field in the Niagara Platform (works from v2.1 hardware version).
	 Improvements: log saving to the Niagara home directory after a watchdog action; Watchdog monitoring of internal processes; MCU firmware update v2.5: Improved UI filtering; Improved UI measurement process.
	 Fixed Bugs: BACnet MSTP high CPU usage; display resolution issue (wrong resolution after a display power loss); display detection issue (no need to restart the controller); passphrase issue (passphrase is now saved on the SD card).
iSMA IO Driver Ver. 2.1.0.0 Release date 31 Mar 2020	 New Functionalities: new temperature sensors support; universal input resistance offset, linear conversion, custom table; analog output linear conversion; DIP switch and rotary switch components added to the LocalIO.

iSMA-B-MAC36NL Software Bundle 1.1

4 Apr 2019



The list below contains modifications and new features since the release of software bundle version 1.0.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.1 Release date 4 Apr 2019	New Functionalities: web engine with keyboard and screensaver with standby via HDMI port; autologin function; web control panel; restore default settings by DIP switch. Improvements: autologin process.
iSMA HDMI Driver Ver. 1.0.10.0 Release date 4 Apr 2019	First release.

iSMA-B-MAC36NL Software Bundle 1.0

7 Feb 2019

The list below contains modifications and new features since the release of the factory software bundle version.

NAME	DESCRIPTION
iSMA-B-MAC36NL Ver. 1.0 (Build 936) Release date 7 Feb 2019	New Functionalities:
iSMA IO Driver Ver. 1.1.4.3 Release date 28 Jan 2019	 Fixed Bugs: fixed errors while starting station containing iSMA_IO components; fixed errors while input reading.

NAME	DESCRIPTION
iSMA-B-MAC36NL Factory Software Bundle (Build 665) Release date 9 Oct 2018	 First release; support for Niagara 4.4.
iSMA IO Driver Ver. 1.1.3.0 Release date 9 Oct 2018	First release.