

MAC36NL SOFTWARE BUNDLE 1.1 04.04.2019

The list below contains modifications and new features since the release of software bundle 1.0.

Name	Description
Software Bundle ver. 1.1 (build 983) Release date 04.04.2019	New functions: <ul style="list-style-type: none">• Web engine with keyboard and screensaver with standby via HDMI port• Autologin function• Web control panel• Restore default settings by dipswitch Improvements: <ul style="list-style-type: none">• Autologin process
iSMA HDMI Driver ver. 1.0.10.0 Release date 04.04.2019	<ul style="list-style-type: none">• First release

MAC36NL SOFTWARE BUNDLE 1.0 07.02.2019

The list below contains modifications and new features since the release of factory software bundle.

Name	Description
<p>Software Bundle ver. 1.0 (build 936)</p> <p>Release date 07.02.2019</p>	<p>New functions:</p> <ul style="list-style-type: none"> • Support for Niagara 4.6 and 4.7 • Data Recovery Service for all supported Niagara versions • BACnet MS/TP support • Access to services using IP ports 1 – 1024 • Device serial number / hardware version displayed in Niagara Platform <p>Improvements:</p> <ul style="list-style-type: none"> • Major performance increase • Numerous security changes • Stability and noise immunity improvements <p>Fixed bugs:</p> <ul style="list-style-type: none"> • Serial port connection issues, 76800 baud rate support added • BACnet IP timeouts • Multicast errors during station startup
<p>iSMA IO Driver ver. 1.1.4.3</p> <p>Release date 28.01.2019</p>	<p>Fixed bugs:</p> <ul style="list-style-type: none"> • Fixed errors while starting station containing iSMA-IO components • Fixed errors while input reading

MAC36NL FACTORY SOFTWARE BUNDLE 09.10.2018

Name	Description
Factory Software Bundle (build 665) Release date 09.10.2018	<ul style="list-style-type: none">• First release• Support for Niagara 4.4
iSMA IO Driver ver. 1.1.3.0 Release date 09.10.2018	<ul style="list-style-type: none">• First release