

## FIRMWARE VERSION

The list below contains modifications and new features:

Name	Description
<b>Firmware version 1.5</b>  Release date 11.02.2019	<b>New functions:</b> <ul style="list-style-type: none"> <li>• Added MBUS BAUD RATE (32 – bits) registers</li> <li>• Added MBUS CONNECTION TIMEOUT (32 – bits) registers</li> </ul> <b>Improvements:</b> <ul style="list-style-type: none"> <li>• Improvement of operational stability</li> </ul>
<b>Firmware version 1.4</b>  Release date 15.10.2018	<b>Fixed bugs:</b> <ul style="list-style-type: none"> <li>• Fixed error reading of MBus frames larger than 255 Bytes</li> <li>• Added function of bootloader input - Modbus address 0x00 value 0x4FF</li> </ul>
<b>Firmware version 1.3</b>  Release date 30.07.2018	<b>Improvements:</b> <ul style="list-style-type: none"> <li>• Improved MAC address display</li> </ul> <b>Fixed bugs:</b> <ul style="list-style-type: none"> <li>• Fixed Modbus TCP/IP socket timeout issue</li> </ul>
<b>Firmware version 1.1</b>  Release date 14.12.2017	<b>New functions:</b> <ul style="list-style-type: none"> <li>• Added new Modbus registers: HW version, MAC address;</li> <li>• Added RS485_BIASING bit in STOP_BITS register;</li> <li>• Added possibility to deactivate RS485_BIASING in hardware version 2.5 and newer</li> <li>• Added new elements on built-in web page: HW version, RS485 biasing;</li> </ul> <b>Improvements:</b> <ul style="list-style-type: none"> <li>• Improved Ethernet communication in Modbus Gateway and M-BUS Gateway mode;</li> </ul>
<b>Firmware version 1.0</b>  Release date 13.01.2017	First release

